

Crew/Trade: **Electricians**

Task/Hazards Examples	PPE	PSU Practice	Regulations
<ul style="list-style-type: none"> Projectiles 	Safety Glasses	Safety glasses are stocked in Stores and provided as needed. PSU will provide prescription safety eyewear only when the supervisor and EHS determine that eye protection worn over prescription lenses does not provide adequate protection.	OAR 437-002-0134(1)(a)(A) OAR 437-002-0134(8)(a-e) OAR 437-002-0134(4)(b)
<ul style="list-style-type: none"> Working with tools Sharp objects Pinching hazards Cold and/or wet weather 	Gloves (leather, nitrile, general work. Insulated, waterproof)	Gloves to address a variety of hazards are stocked in Stores and provided as needed. Specialized gloves for non-routine hazards will be provided with supervisor approval.	OAR 437-002-0134(1)(a)(A) OAR 437-002-0134(4)(d)(C) OAR 437 437-002-0134(12)(a-c)
<ul style="list-style-type: none"> Electrical hazards 	Gloves (electrical hazards)	PSU provides appropriate protective gloves when employees are exposed to electrical hazards.	OAR 437-0020-0134(1)(a)(A) 29CFR 1910.137(a)(1)(i-iv)
<ul style="list-style-type: none"> Crawling, working on knees Accessing equipment located near floor or in crawl spaces 	Knee Pads	Knee pads are stocked in Stores and provided as needed.	OAR 437-002-0134(1)(a)(A)
<ul style="list-style-type: none"> Working around loud equipment or construction activities 	Hearing Protection	Hearing protection including ear plugs and ear muffs are stocked in Stores and provided as needed. Specialized hearing protection (such as different sizes or styles) will be provided with supervisor approval.	29CFR 1910.95(a-b)
<ul style="list-style-type: none"> Working at construction sites, around open ceilings, or in other areas with overhead hazards 	Hard Hats	Hard hats are stocked in Stores and provided as needed.	OAR 437-002-0134(1)(a)(A) OAR 437-002-0134(9)(a)
<ul style="list-style-type: none"> Working on construction sites Working with heavy equipment Puncture hazards such as metal and nails 	Sturdy Shoes/Boots	Sturdy, closed-toe shoes are a minimum requirement for on-the-job safety and are provided by the employee.	OAR 437-002-0134(1)(a)(A) OAR 437-002-0134(4)(b)
<ul style="list-style-type: none"> Electrical hazards 	Electrical Hazard Foot Protection	PSU provides rubber mats if hot work is to be performed. Employees are responsible for providing appropriate footwear for routine electrical work. For specialized electrical hazards, PSU will provide appropriate foot protection as determined by the supervisor and EHS.	OAR 437-002-0134(1)(a)(A) 29CFR 1910.137(1)(i-iv)
<ul style="list-style-type: none"> Crawling Working at construction sites or other areas with protruding nails or sharp objects Working in areas with laceration or burn hazards 	Heavy Pants/Coveralls	PSU provides two pairs of heavy pants or bibs a year for employees whose work duties include tasks/hazards like those listed or as determined by the supervisor and EHS.	OAR- 437-002-0134(1)(a)(A) OAR 437--002-0134(11)(a-c)