

### **Overall Description**

Simon Benson House (SBH) is a registered historic building and is not fully accessible. On Floor 1 of SBH, there are no elevators. One accessible entrance to the first floor of SBH can be found on the center west side of the building. This entrance can be accessed via the path from the park at the south end of the building and diverting north along the west side of the building. The main entrance to SBH can be found on the north side of the building via the stairs to the front porch V100.

Lobby L100 is bordered on the north by the front door to the building, on the east by stairwell S100 with access to the second floor, on the south by meeting room 101, and on the west by reception 107. Reception 107 is bordered on the east by lobby L100 and on the south by room 106. Room 106 is bordered on the north by reception 107, on the east by meeting room 101, and on the south by lobby L101.

Lobby L101 is bordered on the north by room 106, on the east by corridor C100 with access to accessible, single-occupancy, all-gender restroom 102 and single-occupancy, all-gender restroom 104, on the south by corridor C101 with access to conference room 105, and on the west by the accessible entrance from the courtyard.

Corridor C100 is bordered on the north at the west end by single-occupancy, all-gender restroom 104, on the east toward the north by accessible, single-occupancy, all-gender restroom 102, on the east toward the south by the exit to side porch V101, on the west toward the south by stairwell S101 with access to the second floor, and on the west toward the north by lobby L101.

Corridor C101 is bordered on the north by lobby L101 and on the south by conference room 105. Conference room 105 is bordered on the north at the west end by corridor C101 with access to lobby L101.

### **Restrooms**

Restrooms are located to the east of lobby L101 in corridor C100. Accessible single-occupancy, all-gender restroom 102 is located at the north end of the east wall of corridor C100. Single-occupancy, all-gender restroom 104 is located at the west end of the north wall of corridor C100.

### **Wheelchair Accessible Entrances and Exits**

SBH is not a fully accessible building. SBH has no elevators. One wheelchair accessible entrance to the first floor of SBH can be found on the center west side of the building. This entrance can be accessed via the path from the park at the south end of the building and diverting north along the west side of the building.

**Elevators**

SBH is not a fully accessible building. SBH has no elevators.

**Stairs**

Stairwell S100 is located in the east of the main building lobby L100. This stairwell provides access to floors 1 and 2 of SBH. Stairwell S101 is located at the south end on the west wall of corridor C100, southwest of the restrooms. This stairwell provides access to floors 1 and 2 of SBH.

### **Overall Description**

SBH is not a fully accessible building. SBH has no elevators. On the second floor of SBH, stairwell S200 with access to the first floor is located in the east of lobby L200. Stairwell S201 is located to the south of corridor C202 with access to the first floor. Stairwell S202 is located at the south end of corridor C200 with access to the third floor. Single-occupancy, all-gender restroom 203 is located in corridor C201, near the center of the second floor within the central circulation.

Lobby L200 is bordered on the north by patio C203. Lobby L200 is bordered to the southeast by stairwell S200 with access to the first floor. Lobby L200 is bordered to the southwest by corridor C200 with access to rooms 200, 201, 202, & 204, corridor C201, and stairwell S202. Lobby L200 is bordered on the west by room 205.

Corridor C200 is bordered on the north by lobby L200 with access to patio C203, stairwell S200, and room 205. Corridor C200 is bordered on the east wall toward the north by room 200, toward the south by stairwell S202 with access to the third floor, and at the south end by room 201. Corridor C200 is bordered on the south by room 202. Corridor C200 is bordered on the west wall, toward the north by room 204, and near the center by corridor C201 with access to the single-occupancy, all-gender restroom 203 and corridor C202.

Corridor C201 is bordered on the east by corridor C200 with access to lobby L200, stairwell S202, and rooms 200, 201, 202, & 204. Corridor C201 is bordered on the south by single-occupancy, all-gender restroom 203. Corridor C201 is bordered on the west by corridor C202 with access to stairwell S201.

Corridor C202 is bordered on the east, at the north end by corridor C201 with access to corridor C200 and single-occupancy, all-gender restroom 203. Corridor C202 is bordered on the south by stairwell S201 with access to the first floor.

### **Restrooms**

Single-occupancy, all-gender restroom 203 is located in corridor C201, near the center of the second floor within the central circulation.

### **Wheelchair Accessible Entrances and Exits**

SBH is not a fully accessible building. SBH has no elevators. There is no wheelchair access to the second floor of SBH.

### **Elevators**

SBH is not a fully accessible building. SBH has no elevators.

**Stairs**

Stairwell S200 is located in the east of the second floor lobby L200. This stairwell provides access to floors 1 and 2 of SBH. Stairwell S201 is located at the south end of corridor C202, west of the restroom. This stairwell provides access to floors 1 and 2 of SBH. Stairwell S202 is located toward the south end of corridor C200. This stairwell provides access to floors 2 and 3 of SBH.

**Overall Description**

SBH is not a fully accessible building. SBH has no elevators. On the third floor of SBH, stairwell S300 with access to the second floor is located near the center of room 300. There is no restroom on the third floor of SBH..

Room 300 is bordered on the south by room 301.

**Restrooms**

There is no restroom on the third floor of SBH..

**Wheelchair Accessible Entrances and Exits**

SBH is not a fully accessible building. SBH has no elevators. There is no wheelchair access to the third floor of SBH.

**Elevators**

SBH is not a fully accessible building. SBH has no elevators.

**Stairs**

Stairwell S300 is located near the center of room 300. This stairwell provides access to floors 2 and 3 of SBH.

**Overall Description**

SBH is not a fully accessible building. SBH has no elevators. There is no roof access.

**Restrooms**

There is no restroom on the roof of SBH..

**Wheelchair Accessible Entrances and Exits**

SBH is not a fully accessible building. SBH has no elevators. There is no roof access.

**Elevators**

SBH is not a fully accessible building. SBH has no elevators.

**Stairs**

There is no roof access.